


ools Required: Pathead survediver, Philips survediver, pliers, wire critiers, wire stippers, electrical tape, safety glasses. Light Source: (4) G0 less Reb 40W Musicam (Vot Include). Indinated Assessibly Time: 15-50 minutes


reparations identity and inspect all parts before beginning installation. Check package content let and diagrams below to be sere all parts are resent. If any parts are missing or damaged, do not attempt to assemble, install, or operate the thiture. Contact customer service for replacement ads.

▲ Warnings and Cautions Turn of electricity at circuit bracker of

Turn off electricity at circuit breaker or main fuse box before installation. Consult a licensed electricisn if in doubt. These instructions are provided for your safety. It is very important you read them completely before installing the fixture. We strongly recommend that a licensed, professional electricism perform the installation.

Disconnect fixture from power source before replacing butte. Make sure butte are given sufficient time to cool before removal.





1 of 2